

2007-07-10

Tuesday, May 22, 2007
2:02 PM

- Roger
 - Coming up to the shutdown.
 - Personnel shortage.
 - May have to descope. Would do maintenance items.
- Proton Source
 - Linac
- Main Injector
 - 92% SS...now 90%.
 - Two weak Pas.
 - Losses - want to turn the machine down at some point.
 - Want to run multibatch SS for one day to the targets. Issue were losses down the AP1 line last time. Want to do this ASAP during the day.